

JOHNSON PLASTICS

1-800-869-7800

TECH TIPS

Cake Pan Lid Sublimating Instructions

- Place the two support pads under the lid.
- Adjust the press height for medium pressure.
- Attach the printed transfer to the lid.
- Cover with plain paper or teflon sheet.
- Press for 45 - 60 seconds at 400 degrees.